



Picture 27: An example of a thin spot



Picture 28: Grassland



Picture 29: An example of a thin spot



Picture 30: IEL Monitoring Wells



Picture 31: Vegetation on perimeter fence



Picture 32: An example of a thin spot



Picture 33: Tree down on fence



Picture 34: Flowering vegetation



Picture 35: Flowering vegetation



Picture 36: Sweet pea



Picture 37: Section of fence on west side of site



Picture 38: Sweet pea



Picture 40: Wet area in western portion of site



Picture 41: Forest area



Picture 42: An example of a thin spot



Picture 43: Debris



Picture 44: Crab apple tree



Picture 45: Grassland and shrubs



Picture 46: Shrubs



Picture 47: Debris



Picture 48: Grass and Forest Area



Picture 49: Day Lily



Picture 50: Forest area, grass, and shrubs



Picture 51: Brush pile



Picture 52: Wildflowers in area next to Cleveland Ave.



Picture 53: Wildflowers in field next to Cleveland Ave.



Picture 54: Wildflowers



Picture 55: Sweet peas along driveway